



**ARVAL**  
BNP PARIBAS GROUP

AC6601

## INSPECTION REPORT

End of contract

### GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 319237                         |
| License plate                 | AC6601                         |
| Vehicle identification number | W1K3F8EB9RN338927              |
| Dossier                       | 2023208010                     |
| Make                          | Mercedes A 180 Business Line A |
| Mileage                       | 31862                          |
| First registration            | 07/03/2024                     |
|                               |                                |
| client availability date      | 31/07/2026                     |
| inspectionDate                | 04/08/2026                     |

### CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | N       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | N       |        |
| Registration certificate  |        | N       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                     | Acceptable |
|---------|------------------------------------------|------------|
| 14      | Bumper Front // Repair & Painting        | N          |
| 91      | Rocker Panel Left // Smart Repair Medium | Y          |
| 133     | Bumper Rear // Painting                  | Y          |

## Damage Pictures



Bumper Rear // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Front // Repair & Painting-scratch + dent