

INSPECTION REPORT

End of contract

GENERAL INFO

File	315904
License plate	2CFE671
Vehicle identification number	W0V7H9EDXN4200073
Dossier	2022 178 052
Make	Opel Crossland 1.2 81kW Elegan
Mileage	34737
First registration	30/06/2022
client availability date	24/06/2026
inspectionDate	15/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
35	Front Bonnet // Polish	Y
61	Wing Front Left // Smart Repair Medium	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
98	Rocker Panel Left / Cover Not Painted / Replace	Y
139	Bumper Rear / Spoiler / Replace	Y
153	Rear Bonnet // Painting	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
225	Side View Mirror Right // Polish	Y
233	Wing Front right // Painting	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
631	Rear Left Door Interior Coating // Repair	N

Damage Pictures



Front Bonnet // Polish-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Rocker Panel Left / Cover Not Painted / Replace-scratch



Door Front Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Rear Left Door Interior Coating // Repair-scratch



Wheel Alloy Rear Left // Repair-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Rear Bonnet // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Rear Right // Polish-scratch



Side View Mirror Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Bumper Front // Polish-scratch



Bumper Rear / Spoiler / Replace-scratch



Wing Front Left // Smart Repair Medium-scratch + dent



Wing Front right // Painting-bad repair