

INSPECTION REPORT

End of contract


GENERAL INFO

File	315915
License plate	2DFA389
Vehicle identification number	YV1PWH1V2P1193806
Dossier	2022049015
Make	Volvo V90 T6 PHEV Core A
Mileage	183561
First registration	28/02/2023
client availability date	25/06/2026
inspectionDate	07/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
272	Bumper Front / Trim Right / Replace	N
186	Wing Rear Right // Polish	N
193	Door Rear Right // Painting	N
208	Rocker Panel Right / Cover Not Painted / Replace	N
38	Front Bonnet / Insulation / Replace	N
60	Wing Front Left // Smart Repair Small	Y
84	Door Front Left // Repair & Painting	N
106	Door Rear Left // Polish	Y
113	Wing Rear Left // Painting	N
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	Y
165	Roof // Polish	Y
214	Door Front Right // Repair & Painting	Y
233	Wing Front right // Painting	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
413	Seat Front Left / Rear Coating / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	N

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Painting-scratch



Rear Bonnet // Painting-scratch



Bumper Rear // Painting-scratch




Light / Rear left / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Dashboard / Steering Wheel / Replace-scratch




Wing Front Left // Smart Repair Small-dent



Door Front Left // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Wing Rear Left // Painting-bad repair



Roof // Polish-Chemical reaction



Front Bonnet / Insulation / Replace-tear



Seat Front Left / Rear Coating / Replace-worn



Bumper Front / Trim Right / Replace-scratch



Bumper Front // Repair & Painting-scratch + dent



Rocker Panel Right / Cover Not Painted / Replace-scratch



Wing Rear Right // Polish-scratch



Door Rear Right // Painting-scratch