

INSPECTION REPORT


End of contract

GENERAL INFO

File	316615
License plate	2BBL218
Vehicle identification number	TMAJD81BGMJ110808
Dossier	2021083003
Make	Hyundai Tuc.T-GDi 48V 110kW Fe
Mileage	153635
First registration	20/09/2021
client availability date	06/07/2026
inspectionDate	09/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
83	Door Front Left // Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
124	Light / Rear left / Replace	N
136	Bumper Rear // Polish	Y
139	Bumper Rear / Spoiler / Replace	N
153	Rear Bonnet // Painting	Y
158	Rear Bonnet / 3rd Stoplight / Replace	N
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
187	Wing Rear Right / Trim / Replace	Y
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
237	Wing Front right / Trim / Replace	N
282	Bumper Rear / Trim Center / Replace	N
541	Interior // Repair 2	Y
561	Dashboard // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	Y

Damage Pictures




Rear Bonnet // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet / 3rd Stoplight / Replace-scratch



Light / Rear Right / Replace-scratch



Bumper Rear // Polish-scratch






Bumper Rear / Trim Center / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Light / Rear left / Replace-scratch



Door Front Left // Painting-scratch



Front Bonnet // Painting-scratch




Wing Front right / Trim / Replace-scratch




Side View Mirror Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch




Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent





Door Front Right // Repair & Painting-scratch + dent



Interior // Repair 2-missing



Interior Cleaning // Small-stain



Key Price Range 2 //-worn



Dashboard // Repair-worn



Wing Rear Right / Trim / Replace-bad position