

INSPECTION REPORT


End of contract


GENERAL INFO

File	316282
License plate	2DQU410
Vehicle identification number	VR3USHNSSNJ840236
Dossier	2023104053
Make	Peugeot 2008 1.2 96kW Active P
Mileage	148823
First registration	30/05/2023
client availability date	25/06/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	N
84	Door Front Left // Repair & Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	N
113	Wing Rear Left // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
161	Roof // Smart Repair Medium	N
165	Roof // Polish	Y
186	Wing Rear Right // Polish	Y
190	Door Rear Right // Smart Repair Small	Y
201	Rocker Panel Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	N
282	Bumper Rear / Trim Center / Replace	N
311	Wheel Alloy Front Left // Repair	Y
341	Wheel Alloy Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
561	Dashboard // Repair	N
611	Front Left Door Interior Coating // Repair	N
621	Front Right Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Trim Center / Replace-scratch



Roof // Polish-scratch



Wing Rear Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Rear Left // Painting-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch







Front Right Door Interior Coating // Repair-scratch




Dashboard // Repair-scratch




Front Left Door Interior Coating // Repair-scratch



Roof // Smart Repair Medium-dent



Door Rear Right // Smart Repair Small-dent




Door Front Right // Repair & Painting-scratch + dent





Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Seat Front Left / Bottom Coating / Replace-Incinerated



Interior Cleaning // Small-stain



Front Bonnet // Painting-stone chipping



Bumper Front // Painting-Chipped paint