

INSPECTION REPORT





End of contract

GENERAL INFO

File	317431
License plate	2AUT510
Vehicle identification number	TMBJF7NU1M5027174
Dossier	2021 200 051
Make	Skoda Karoq 2.0TDi 85kW Ambiti
Mileage	130430
First registration	27/07/2021
client availability date	10/07/2026
inspectionDate	15/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
13	Bumper Front // Painting	N
104	Door Rear Left // Repair & Painting	N
116	Wing Rear Left // Polish	Y
156	Rear Bonnet // Polish	Y
208	Rocker Panel Right / Cover Not Painted / Replace	Y
216	Door Front Right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N


Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet // Polish-scratch



Door Front Right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch




Bumper Front // Painting-scratch



Rocker Panel Right / Cover Not Painted / Replace-dent



Door Rear Left // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain




Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch




Rear Left Door Interior Coating // Replace Completely-scratch



Wing Rear Left // Polish-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch