

INSPECTION REPORT


End of contract

GENERAL INFO

File	317425
License plate	1YHT138
Vehicle identification number	VF3MCYHZRLL056521
Dossier	2020013600
Make	Peugeot 5008 1.5BHDi 96kW GT L
Mileage	106360
First registration	04/09/2020
client availability date	06/07/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	N
272	Bumper Front / Trim Right / Replace	N
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
117	Wing Rear Left / Trim / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
183	Wing Rear Right // Painting	N
191	Door Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	N
225	Side View Mirror Right // Polish	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
273	Bumper Front / Grid Left / Replace	Y
275	Bumper Front / Grid Right / Replace	N
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures




Side View Mirror Right // Polish-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Left // Smart Repair Medium-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Left // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Right // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Wing Rear Right // Painting-bad repair



Bumper Front / Grid Left / Replace-bad position



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Bumper Front / Grid Right / Replace-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch