

# INSPECTION REPORT


**End of contract**

## GENERAL INFO

|                               |                                |
|-------------------------------|--------------------------------|
| File                          | 316306                         |
| License plate                 | 2FHX912                        |
| Vehicle identification number | VF3MCYHZRKS458433              |
| Dossier                       | 2019175039                     |
| Make                          | Peugeot 3008 1.5BHDi 96kW Acti |
| Mileage                       | 89957                          |
| First registration            | 15/11/2019                     |
|                               |                                |
| client availability date      | 25/06/2026                     |
| inspectionDate                | 09/07/2026                     |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | Y       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | N       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                                    | Acceptable |
|---------|---------------------------------------------------------|------------|
| 13      | Bumper Front // Painting                                | Y          |
| 63      | Wing Front Left // Painting                             | Y          |
| 84      | Door Front Left // Repair & Painting                    | Y          |
| 100     | Door Rear Left // Smart Repair Small                    | Y          |
| 194     | Door Rear Right // Repair & Painting                    | Y          |
| 210     | Door Front Right // Smart Repair Small                  | Y          |
| 272     | Bumper Front / Trim Right / Replace                     | N          |
| 310     | Wheel Two Tone Front Left // Repair                     | Y          |
| 320     | Wheel Two Tone Rear Left // Repair                      | N          |
| 330     | Wheel Two Tone Rear Right // Repair                     | N          |
| 340     | Wheel Two Tone Front Right // Repair                    | N          |
| 431     | Seat Rear Left // Repair                                | Y          |
| 540     | Interior // Repair 1                                    | N          |
| 624     | Front Right Door Interior Coating // Replace Completely | Y          |
| 860     | Interior Cleaning // Small                              | N          |

## Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch





Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Wing Front Left // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Seat Rear Left // Repair-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Door Front Right // Smart Repair Small-dent



Door Rear Right // Repair & Painting-dent



Door Rear Left // Smart Repair Small-dent



Door Front Left // Repair & Painting-scratch + dent



Interior // Repair 1-tear



Interior Cleaning // Small-stain