

INSPECTION REPORT

End of contract

GENERAL INFO

File	317515
License plate	1YXR802
Vehicle identification number	W0VEFYHYCLJ883713
Dossier	2020209010
Make	Opel Comb.1.5D 75kW 2.3T L2H1
Mileage	141973
First registration	01/04/2021
client availability date	07/07/2026
inspectionDate	14/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
223	Side View Mirror Right // Replace Not Painted	Y
227	Side View Mirror Right / Shell / Replace Not Painted	Y
13	Bumper Front // Painting	Y
19	Bumper Front / Lower Cover Not Painted / Replace	N
38	Front Bonnet / Insulation / Replace	N
84	Door Front Left // Repair & Painting	N
87	Door Front Left / Trim / Replace	Y
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
162	Roof // Painting	N
163	Roof // Repair & Painting	Y
174	Light / Rear Right / Replace	N
184	Wing Rear Right // Repair & Painting	Y
193	Door Rear Right // Painting	Y
202	Rocker Panel Right // Painting	Y
214	Door Front Right // Repair & Painting	N
294	Rear Loading Door Left // Repair & Painting	N
304	Rear Loading Door Right // Repair & Painting	N
422	Seat Front Right / Bottom Coating / Replace	Y
423	Seat Front Right / Rear Coating / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	N
624	Front Right Door Interior Coating // Replace Completely	Y
629	Front Right Door Interior Coating / Control Module / Replace	N
860	Interior Cleaning // Small	N



Damage Pictures




Bumper Front // Painting-scratch



Door Front Left / Trim / Replace-scratch



Door Rear Left // Polish-scratch



Wing Rear Left // Polish-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Door Front Left // Repair & Painting-dent




Wing Rear Right // Repair & Painting-dent






Bumper Front / Lower Cover Not Painted / Replace-dent






Roof // Repair & Painting-dent





Rear Loading Door Left // Repair & Painting-scratch + dent





Rear Loading Door Right // Repair & Painting-scratch + dent



Trunk Compartment / Side Cover Left / Replace-scratch + dent




Trunk Compartment / Side Cover Right / Replace-scratch
+ dent









Door Front Right // Repair & Painting-scratch + dent




Front Right Door Interior Coating / Control Module /
Replace-cracked




Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Seat Front Right / Bottom Coating / Replace-worn



Dashboard / Steering Wheel / Replace-worn






Seat Front Right / Rear Coating / Replace-bad position



Trunk Lid Interior Coating / MDF Rear Left / Replace-bad position



Roof // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch



Light / Rear left / Replace-scratch



Light / Rear Right / Replace-scratch




Door Rear Right // Painting-scratch



Rocker Panel Right // Painting-scratch



Side View Mirror Right // Replace Not Painted-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch