

INSPECTION REPORT

End of contract


GENERAL INFO

File	316504
License plate	2ABK719
Vehicle identification number	VR3FCYHZTMY001678
Dossier	2020 272 055
Make	Peugeot 508SW 1.5 BHDi Allur.P
Mileage	87584
First registration	09/02/2021
client availability date	07/07/2026
inspectionDate	30/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
71	Side View Mirror Left // Plastic Repair	N
72	Side View Mirror Left // Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	N
84	Door Front Left // Repair & Painting	N
104	Door Rear Left // Repair & Painting	N
801	See External Expertise	N
13	Bumper Front // Painting	N
32	Front Bonnet // Painting	N
41	Windshield // Replace	Y
114	Wing Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
133	Bumper Rear // Painting	N
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	N
236	Wing Front right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
422	Seat Front Right / Bottom Coating / Replace	Y
431	Seat Rear Left // Repair	Y
432	Seat Rear Left / Bottom Coating / Replace	Y
538	Trunk Compartment / Boot Cover / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
634	Rear Left Door Interior Coating // Replace Completely	Y
859	Display Navigation-Radio // Replace	Y

Damage Pictures



Door Front Right // Repair & Painting-bad repair



Trunk Compartment / Boot Cover / Replace-missing



Front Bonnet // Painting-Chemical reaction



Seat Front Right / Bottom Coating / Replace-worn



Seat Rear Left / Bottom Coating / Replace-worn



Seat Rear Left // Repair-scratch



Rear Left Door Interior Coating // Replace Completely-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Dashboard / Steering Wheel / Replace-scratch




Display Navigation-Radio // Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch



Wing Front right // Polish-scratch



Windshield // Replace-scratch





Wheel Two Tone Rear Right // Repair-scratch




Wheel Two Tone Front Right // Repair-scratch



Bumper Front // Painting-scratch




Rocker Panel Right // Smart Repair Medium-scratch






Wheel Two Tone Rear Left // Repair-scratch



Bumper Rear // Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent




Door Rear Right // Repair & Painting-scratch + dent





Side View Mirror Left // Plastic Repair-scratch



Side View Mirror Left // Painting-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch









See External Expertise-Splashes



Door Front Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent