

INSPECTION REPORT

End of contract


GENERAL INFO

File	317817
License plate	2CCJ986
Vehicle identification number	VF3MRHNSUNS058222
Dossier	2022 101 068
Make	Peugeot 3008 1.2PTech 96kW GT
Mileage	128013
First registration	02/06/2022
client availability date	01/06/2026
inspectionDate	20/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	N
38	Front Bonnet / Insulation / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	N
125	Light / Rear Left On Rear Bonnet / Replace	Y
134	Bumper Rear // Repair & Painting	N
184	Wing Rear Right // Repair & Painting	N
193	Door Rear Right // Painting	Y
197	Door Rear Right / Trim / Replace	Y
225	Side View Mirror Right // Polish	Y
340	Wheel Two Tone Front Right // Repair	Y
538	Trunk Compartment / Boot Cover / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Front / Spoiler / Replace-scratch



Bumper Front // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Side View Mirror Right // Polish-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch



Door Rear Left // Painting-scratch




Bumper Rear // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent




Wing Rear Right // Repair & Painting-scratch + dent



Trunk Compartment / Boot Cover / Replace-missing



Front Bonnet / Insulation / Replace-tear



Interior Cleaning // Small-stain



Lettering Removal 15min-Remainder stickers