

INSPECTION REPORT


End of contract

GENERAL INFO

File	316978
License plate	1YQB117
Vehicle identification number	VF3MRHNSMLS246629
Dossier	2020 184 069
Make	Peugeot 5008 1.2PTech 96kW All
Mileage	136151
First registration	02/11/2020
client availability date	01/07/2026
inspectionDate	08/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	







DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	N
41	Windshield // Replace	N
54	Headlight / Front left / Replace	Y
100	Door Rear Left // Smart Repair Small	Y
114	Wing Rear Left // Repair & Painting	N
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
165	Roof // Polish	Y
180	Wing Rear Right // Smart Repair Small	Y
187	Wing Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
217	Door Front Right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N


Damage Pictures



Bumper Rear // Polish-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Door Front Right / Trim / Replace-scratch



Door Front Right // Polish-scratch



Headlight / Front left / Replace-scratch



Windshield // Replace-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Wing Rear Right // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Roof // Polish-Chemical reaction



Seat Front Left / Bottom Coating / Replace-worn



Trunk Lid Interior Coating / Complete Panel / Replace-bad position



Front Bonnet / Insulation / Replace-hole