

INSPECTION REPORT



End of contract

GENERAL INFO

File	315842
License plate	2DEQ886
Vehicle identification number	VXKF3DGXTP1001282
Dossier	2022 294 090
Make	Opel Astra 1.6PHEV 132kW Bus.E
Mileage	117009
First registration	23/02/2023
client availability date	23/06/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
81	Door Front Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
165	Roof // Polish	Y
183	Wing Rear Right // Painting	Y
190	Door Rear Right // Smart Repair Small	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
771	Interior / Floor Mats / Replacement	Y


Damage Pictures



Front Bonnet // Polish-scratch



Wing Rear Right // Painting-scratch



Door Rear Right // Smart Repair Small-dent



Door Rear Left // Smart Repair Small-dent



Wheel Two Tone Rear Left // Repair-Chemical reaction




Door Front Left // Smart Repair Medium-Chemical reaction



Wheel Two Tone Front Left // Repair-Chemical reaction



Wheel Two Tone Front Right // Repair-Chemical reaction



Wheel Two Tone Rear Right // Repair-Chemical reaction



Interior / Floor Mats / Replacement-worn



Roof // Polish-scratch



Bumper Front // Painting-scratch



Bumper Front // Smart Repair Large-scratch