

INSPECTION REPORT



End of contract

GENERAL INFO

File	317824
License plate	2CCF885
Vehicle identification number	VF3YDBPAU12U99425
Dossier	2021 200 071
Make	Peugeot Boxer 435 L3 140 BHDi
Mileage	9700
First registration	01/06/2022
client availability date	15/07/2026
inspectionDate	03/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
63	Wing Front Left // Painting	Y
77	Side View Mirror Left / Shell / Replace Not Painted	Y
92	Rocker Panel Left // Painting	Y
134	Bumper Rear // Repair & Painting	Y
540	Interior // Repair 1	N
592	Trunk Lid Interior Coating / MDF Rear Left / Replace	Y
860	Interior Cleaning // Small	N


Damage Pictures




Wing Front Left // Painting-scratch





Side View Mirror Left / Shell / Replace Not Painted-scratch



Rocker Panel Left // Painting-scratch



Trunk Lid Interior Coating / MDF Rear Left / Replace-cracked



Bumper Rear // Repair & Painting-rust



Interior // Repair 1-tear



Interior Cleaning // Small-stain