

INSPECTION REPORT


End of contract


GENERAL INFO

File	316057
License plate	2BLP074
Vehicle identification number	W1K2470841J329147
Dossier	2021 099 057
Make	Mercedes B 180 Bus.Sol.Essen.
Mileage	110720
First registration	05/01/2022
client availability date	26/06/2026
inspectionDate	10/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
230	Wing Front right // Smart Repair Small	N
186	Wing Rear Right // Polish	N
194	Door Rear Right // Repair & Painting	N
216	Door Front Right // Polish	N
35	Front Bonnet // Polish	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
134	Bumper Rear // Repair & Painting	N
165	Roof // Polish	Y
174	Light / Rear Right / Replace	N
217	Door Front Right / Trim / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
840	Interior Cleaning // Large	N

Damage Pictures




Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Front Left // Repair-scratch




Side View Mirror Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Polish-scratch



Roof // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Door Front Right / Trim / Replace-scratch



Light / Rear Right / Replace-scratch




Light / Rear left / Replace-scratch




Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent




Front Bonnet // Polish-Chemical reaction



Interior Cleaning // Large-dirty



Wing Front right // Smart Repair Small-dent



Bumper Front // Repair & Painting-cracked



Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right // Polish-scratch



Door Front Right // Polish-scratch