

INSPECTION REPORT



End of contract

GENERAL INFO

File	316165
License plate	2CKH185
Vehicle identification number	W1KAH0DB9PF070733
Dossier	2021 273 024
Make	Mercedes C Break 200 d 120kW B
Mileage	131757
First registration	23/08/2022
client availability date	29/06/2026
inspectionDate	14/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
66	Wing Front Left // Polish	Y
72	Side View Mirror Left // Painting	N
81	Door Front Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	N
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
211	Door Front Right // Smart Repair Medium	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
411	Seat Front Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
774	Interior / Side Cover rear Seat / Replace	Y



Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Painting-scratch



Seat Front Left // Repair-scratch



Door Front Left // Smart Repair Medium-scratch



Side View Mirror Left // Painting-scratch



Wing Front Left // Polish-scratch



Bumper Front // Smart Repair Large-scratch



Interior / Side Cover rear Seat / Replace-scratch



Door Front Right // Smart Repair Medium-scratch




Door Rear Right // Painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent