

INSPECTION REPORT

End of contract

GENERAL INFO

File	316191
License plate	2AUB588
Vehicle identification number	W1K1186031N167516
Dossier	2021138099
Make	Mercedes CLA SB 180 d Aut
Mileage	110932
First registration	16/07/2021
client availability date	03/07/2026
inspectionDate	07/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
72	Side View Mirror Left // Painting	N
78	Side View Mirror Left / Direction Indicator / Replace	N
80	Door Front Left // Smart Repair Small	N
93	Rocker Panel Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	N
134	Bumper Rear // Repair & Painting	N
154	Rear Bonnet // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	N
184	Wing Rear Right // Repair & Painting	Y
194	Door Rear Right // Repair & Painting	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
551	Central Console // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Front Right // Repair-scratch



Central Console // Repair-scratch



Light / Rear left / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch




Door Front Left // Smart Repair Small-dent



Rocker Panel Left // Repair & Painting-dent




Rear Bonnet // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent




Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent





Wing Rear Left // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Rear Bonnet / Rear Window / Replace-scratch



Side View Mirror Left // Painting-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch