

INSPECTION REPORT

End of contract


GENERAL INFO

File	318251
License plate	VG9875
Vehicle identification number	VSKHAAME0U0627418
Dossier	2020 184 013
Make	Nissan *E-NV200 Fg Optima SSD
Mileage	55237
First registration	08/02/2021
client availability date	16/07/2026
inspectionDate	27/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
19	Bumper Front / Lower Cover Not Painted / Replace	N
80	Door Front Left // Smart Repair Small	Y
114	Wing Rear Left // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
174	Light / Rear Right / Replace	N
194	Door Rear Right // Repair & Painting	N
227	Side View Mirror Right / Shell / Replace Not Painted	Y
294	Rear Loading Door Left // Repair & Painting	Y
304	Rear Loading Door Right // Repair & Painting	N
314	Wheel Front Left / Wheel Cover / Replace	Y
324	Wheel Rear Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	Y
344	Wheel Front Right / Wheel Cover / Replace	N
412	Seat Front Left / Bottom Coating / Replace	Y
554	Central Console // Replace Completely	Y
565	Dashboard / Storage Tray / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
624	Front Right Door Interior Coating // Replace Completely	Y
883	Key Price Range 2 //	N

Damage Pictures



Light / Rear Right / Replace-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Front // Painting-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch




Front Right Door Interior Coating // Replace Completely-scratch



Dashboard / Storage Tray / Replace-scratch



Central Console // Replace Completely-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch



Front Left Door Interior Coating // Replace Completely-scratch





Wing Rear Left // Repair & Painting-dent



Rear Loading Door Left // Repair & Painting-scratch + dent



Rear Loading Door Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Wheel Front Right / Wheel Cover / Replace-cracked



Bumper Rear / Lower Cover Not Painted / Replace-bad position



Bumper Front / Lower Cover Not Painted / Replace-bad position



Seat Front Left / Bottom Coating / Replace-hole