

INSPECTION REPORT





End of contract


GENERAL INFO

File	318145
License plate	2CEK280
Vehicle identification number	TMBJG7NXXNY114790
Dossier	2021180040
Make	Skoda Oct.Com.2.0TDI 85kW Clev
Mileage	97227
First registration	23/06/2022
client availability date	16/07/2026
inspectionDate	23/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
33	Front Bonnet // Repair & Painting	Y
63	Wing Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	Y
116	Wing Rear Left // Polish	Y
151	Rear Bonnet // Smart Repair Medium	N
183	Wing Rear Right // Painting	Y
191	Door Rear Right // Smart Repair Medium	N
216	Door Front Right // Polish	Y
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
544	Interior / Floor Covering / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	N

Damage Pictures



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Left // Polish-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wing Front Left // Painting-scratch




Rear Right Door Interior Coating // Replace Completely-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Polish-scratch



Wing Rear Right // Painting-scratch



Rocker Panel Left // Smart Repair Medium-dent



Door Rear Right // Smart Repair Medium-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Rear Bonnet // Smart Repair Medium-scratch + dent



Interior / Floor Covering / Replace-hole