

INSPECTION REPORT

End of contract



GENERAL INFO

File	319056
License plate	2DEW314
Vehicle identification number	VXKFPHNPLP1008808
Dossier	2022 192 200
Make	Opel Astra 1.2 81kW Edition
Mileage	37968
First registration	27/02/2023
client availability date	30/07/2026
inspectionDate	03/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
801	See External Expertise	Y
100	Door Rear Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
214	Door Front Right // Repair & Painting	Y
233	Wing Front right // Painting	Y
311	Wheel Alloy Front Left // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
840	Interior Cleaning // Large	Y


Damage Pictures



Door Front Right // Repair & Painting-scratch + dent



Door Rear Right // Painting-bad repair



Bumper Rear // Painting-bad repair



Wing Rear Right // Painting-bad repair



Wing Front right // Painting-bad repair



Interior Cleaning // Large-dirty



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Rear Left // Smart Repair Small-dent





See External Expertise-dent