

INSPECTION REPORT

End of contract

GENERAL INFO

File	311945
License plate	2EAU550
Vehicle identification number	KMHC751DGKU143321
Dossier	2018289168
Make	Hyundai Ioniq 1.6GDi Plug-in H
Mileage	98216
First registration	21/03/2019
client availability date	07/05/2026
inspectionDate	18/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
38	Front Bonnet / Insulation / Replace	Y
80	Door Front Left // Smart Repair Small	N
91	Rocker Panel Left // Smart Repair Medium	N
134	Bumper Rear // Repair & Painting	Y
152	Rear Bonnet // Smart Repair Large	N
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
222	Side View Mirror Right // Painting	N
271	Bumper Front / Trim Left / Replace	Y
282	Bumper Rear / Trim Center / Replace	Y
311	Wheel Alloy Front Left // Repair	Y
314	Wheel Front Left / Wheel Cover / Replace	Y
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	Y
334	Wheel Rear Right / Wheel Cover / Replace	Y
341	Wheel Alloy Front Right // Repair	Y
344	Wheel Front Right / Wheel Cover / Replace	Y
346	Tyre Front Right // Replace	Y
422	Seat Front Right / Bottom Coating / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	N
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	N
634	Rear Left Door Interior Coating // Replace Completely	Y
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures



Roof // Polish-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Alloy Front Right // Repair-scratch




Side View Mirror Right // Painting-scratch



Trunk Compartment / Side Cover Right / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior // Repair 1-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Door Front Left // Smart Repair Small-dent



Rear Bonnet // Smart Repair Large-scratch + dent



Bumper Rear / Trim Center / Replace-scratch + dent



Bumper Rear // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Front Bonnet / Insulation / Replace-tear



Front Left Door Interior Coating // Replace Completely-tear



Tyre Front Right // Replace-tear



Seat Front Right / Bottom Coating / Replace-worn