

INSPECTION REPORT

End of contract

GENERAL INFO

File	319058
License plate	2DRQ653
Vehicle identification number	VR3FRHNSLPY556530
Dossier	2022 188 157
Make	Peugeot 308 SW 1.2 130 Active
Mileage	68438
First registration	05/06/2023
client availability date	30/07/2026
inspectionDate	03/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
35	Front Bonnet // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
161	Roof // Smart Repair Medium	Y
194	Door Rear Right // Repair & Painting	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y


Damage Pictures




Wing Front right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Roof // Smart Repair Medium-dent



Door Rear Right // Repair & Painting-scratch + dent



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front // Polish-scratch



Front Bonnet // Polish-scratch