

INSPECTION REPORT

End of contract

GENERAL INFO

File	316977
License plate	2CLV581
Vehicle identification number	KMHC851CGNU287951
Dossier	2022 039 143
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	78976
First registration	08/09/2022
client availability date	02/07/2026
inspectionDate	10/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
311	Wheel Alloy Front Left // Repair	N
316	Tyre Front Left // Replace	N
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
86	Door Front Left // Polish	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
136	Bumper Rear // Polish	Y
165	Roof // Polish	Y
193	Door Rear Right // Painting	Y
233	Wing Front right // Painting	Y
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
452	Seat Rear Right / Bottom Coating / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
538	Trunk Compartment / Boot Cover / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Interior Cleaning // Small-stain




Bumper Front / Spoiler / Replace-bad repair



Bumper Front // Painting-bad repair



Seat Rear Right / Bottom Coating / Replace-Incinerated



Roof // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Front right // Painting-scratch



Door Rear Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Polish-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Compartment / Boot Cover / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Tyre Front Left // Replace-tear