

INSPECTION REPORT


End of contract


GENERAL INFO

File	315846
License plate	2ABE700
Vehicle identification number	W1K2050001R612576
Dossier	2019352076
Make	Mercedes C 180 d 90kW Aut.Bus.
Mileage	55687
First registration	08/02/2021
client availability date	23/06/2026
inspectionDate	02/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
14	Bumper Front // Repair & Painting	N
33	Front Bonnet // Repair & Painting	N
54	Headlight / Front left / Replace	N
66	Wing Front Left // Polish	Y
80	Door Front Left // Smart Repair Small	Y
116	Wing Rear Left // Polish	Y
134	Bumper Rear // Repair & Painting	N
157	Rear Bonnet / Trim / Replace	Y
180	Wing Rear Right // Smart Repair Small	N
205	Rocker Panel Right // Polish	Y
208	Rocker Panel Right / Cover Not Painted / Replace	N
244	Light / Front Right / Replace	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N
540	Interior // Repair 1	Y
551	Central Console // Repair	Y
614	Front Left Door Interior Coating // Replace Completely	Y
621	Front Right Door Interior Coating // Repair	Y
631	Rear Left Door Interior Coating // Repair	N
631	Rear Left Door Interior Coating // Repair	Y
641	Rear Right Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	Y
773	Interior / A Pillar Lower Cover / Replace	Y

Damage Pictures



Rocker Panel Right / Cover Not Painted / Replace-scratch



Rocker Panel Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch




Light / Front Right / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Wing Rear Left // Polish-scratch



Rear Right Door Interior Coating // Repair-scratch



Rear Right Door Interior Coating // Repair-scratch



Front Right Door Interior Coating // Repair-scratch



Central Console // Repair-scratch



Interior / A Pillar Lower Cover / Replace-scratch



Rear Bonnet / Trim / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Headlight / Front left / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Rear Left Door Interior Coating // Repair-scratch





Front Left Door Interior Coating // Replace Completely-scratch



Bumper Rear // Repair & Painting-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Wing Rear Right // Smart Repair Small-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Interior // Repair 1-bad position



Door Front Right // Polish-scratch



Wing Front right // Polish-scratch



Side View Mirror Right // Painting-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch