

INSPECTION REPORT



End of contract

GENERAL INFO

File	315718
License plate	2CAD041
Vehicle identification number	VF7YDCPFC12U90737
Dossier	2021316040
Make	Citroen Ju.4-35 L4H3 2.2Hdi 16
Mileage	136204
First registration	06/05/2022
client availability date	03/07/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
227	Side View Mirror Right / Shell / Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
184	Wing Rear Right // Repair & Painting	N
187	Wing Rear Right / Trim / Replace	N
191	Door Rear Right // Smart Repair Medium	N
194	Door Rear Right // Repair & Painting	N
294	Rear Loading Door Left // Repair & Painting	Y
304	Rear Loading Door Right // Repair & Painting	Y
77	Side View Mirror Left / Shell / Replace Not Painted	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
124	Light / Rear left / Replace	N
137	Bumper Rear // Replace without painting	Y
272	Bumper Front / Trim Right / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Light / Rear left / Replace-cracked




Interior Cleaning // Small-stain



Bumper Front / Trim Right / Replace-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Bumper Rear // Replace without painting-scratch



Side View Mirror Right / Shell / Replace Not Painted-cracked



Side View Mirror Right / Direction Indicator / Replace-cracked




Rear Loading Door Right // Repair & Painting-hole




Rear Loading Door Left // Repair & Painting-hole



Wing Rear Right / Trim / Replace-missing






Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-hole



Door Rear Right // Smart Repair Medium-hole