



ARVAL
BNP PARIBAS GROUP

2FDZ506

INSPECTION REPORT

End of contract

GENERAL INFO

File	314561
License plate	2FDZ506
Vehicle identification number	JTPAAAAA20R024104
Dossier	2024065003
Make	Toyota C-HR 1.8 Hybrid Dyn.Pl.
Mileage	30549
First registration	08/04/2024
client availability date	11/06/2026
inspectionDate	07/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
187	Wing Rear Right / Trim / Replace	N
197	Door Rear Right / Trim / Replace	N
196	Door Rear Right // Polish	Y
216	Door Front Right // Polish	Y
33	Front Bonnet // Repair & Painting	N
63	Wing Front Left // Painting	Y
83	Door Front Left // Painting	N
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
180	Wing Rear Right // Smart Repair Small	N
330	Wheel Two Tone Rear Right // Repair	Y
860	Interior Cleaning // Small	N

Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Wing Rear Left // Painting-scratch



Door Front Left / Trim / Replace-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Wing Front Left // Painting-scratch



Rocker Panel Left // Smart Repair Medium-scratch




Front Bonnet // Repair & Painting-dent




Wing Rear Right // Smart Repair Small-scratch + dent



Interior Cleaning // Small-stain



Door Rear Right / Trim / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Door Front Right // Polish-scratch



Door Rear Right // Polish-scratch