

INSPECTION REPORT




End of contract

GENERAL INFO

File	315275
License plate	2CEG129
Vehicle identification number	KMHC751DGNU292035
Dossier	2022 003 052
Make	Hyundai Ioniq 1.6GDi PHEV Shin
Mileage	114224
First registration	22/06/2022
client availability date	18/06/2026
inspectionDate	03/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
186	Wing Rear Right // Polish	Y
191	Door Rear Right // Smart Repair Medium	Y
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
13	Bumper Front // Painting	Y
18	Bumper Front / Spoiler / Replace	Y
38	Front Bonnet / Insulation / Replace	Y
41	Windshield // Replace	Y
110	Wing Rear Left // Smart Repair Small	Y
133	Bumper Rear // Painting	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wing Rear Left // Smart Repair Small-dent



Bumper Rear // Painting-scratch



Wing Front right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Windshield // Replace-cracked



Wheel Two Tone Front Left // Repair-Chemical reaction



Wheel Two Tone Rear Left // Repair-Chemical reaction



Wheel Two Tone Rear Right // Repair-Chemical reaction



Front Bonnet / Insulation / Replace-tear



Bumper Front / Spoiler / Replace-Chipped paint



Bumper Front // Painting-scratch




Light / Rear Left On Rear Bonnet / Replace-cracked



Light / Rear left / Replace-cracked



Wing Rear Right // Polish-scratch



Door Rear Right // Smart Repair Medium-dent



Light / Rear Right On Rear Bonnet / Replace-cracked



Light / Rear Right / Replace-cracked