

INSPECTION REPORT



End of contract

GENERAL INFO

File	318062
License plate	2AVV660
Vehicle identification number	VF3MCYHZUML042429
Dossier	2020357022
Make	Peugeot 5008 1.5BHdi 96kW GT P
Mileage	138602
First registration	09/08/2021
client availability date	14/07/2026
inspectionDate	03/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
54	Headlight / Front left / Replace	N
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
100	Door Rear Left // Smart Repair Small	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
159	Rear Bonnet / Rear Window / Replace	N
184	Wing Rear Right // Repair & Painting	Y
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
222	Side View Mirror Right // Painting	N
237	Wing Front right / Trim / Replace	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Headlight / Front left / Replace-scratch



Front Bonnet // Polish-scratch




Bumper Front // Polish-scratch



Wing Front right / Trim / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Side View Mirror Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rocker Panel Left // Smart Repair Medium-dent




Door Rear Left // Smart Repair Small-dent



Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right / Trim / Replace-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Interior // Repair 1-bad repair



Front Bonnet / Insulation / Replace-cracked



Wheel Two Tone Rear Left // Repair-Chemical reaction