

INSPECTION REPORT






End of contract

GENERAL INFO

File	316983
License plate	2CJN275
Vehicle identification number	VSSZZZKLZNR033548
Dossier	2022200045
Make	Seat Leon ST 1.5eTSI 150 FR DS
Mileage	38935
First registration	11/08/2022
client availability date	06/07/2026
inspectionDate	13/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
16	Bumper Front // Polish	Y
18	Bumper Front / Spoiler / Replace	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
111	Wing Rear Left // Smart Repair Medium	Y
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
544	Interior / Floor Covering / Replace	Y
774	Interior / Side Cover rear Seat / Replace	Y

Damage Pictures



Interior / Floor Covering / Replace-Incinerated



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Smart Repair Medium-scratch



Bumper Front / Spoiler / Replace-scratch




Bumper Front // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch




Door Rear Left // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Rocker Panel Left // Smart Repair Medium-dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Bumper Rear // Repair & Painting-cracked