

INSPECTION REPORT



End of contract


GENERAL INFO

File	317087
License plate	2ARJ811
Vehicle identification number	W0V7D9EE1M4191301
Dossier	2021 105 037
Make	Opel Crossland 1.2 61kW Editio
Mileage	84575
First registration	21/06/2021
client availability date	02/07/2026
inspectionDate	31/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	N
134	Bumper Rear // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
165	Roof // Polish	Y
174	Light / Rear Right / Replace	N
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
234	Wing Front right // Repair & Painting	N
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	Y
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
634	Rear Left Door Interior Coating // Replace Completely	Y

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Repair & Painting-scratch



Light / Rear left / Replace-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Wing Rear Left // Polish-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Light / Rear Right / Replace-scratch




Door Front Right // Smart Repair Small-scratch



Door Rear Right // Painting-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Wing Rear Right // Painting-scratch



Wheel Front Right / Wheel Cover / Replace-scratch




Roof // Smart Repair Medium-dent




Rocker Panel Right // Smart Repair Medium-dent



Bumper Front // Repair & Painting-bad repair



Wing Front right // Repair & Painting-bad repair



Roof // Polish-Chemical reaction