

INSPECTION REPORT




End of contract

GENERAL INFO

File	318146
License plate	2DPG782
Vehicle identification number	VR3UPMHDP5042493
Dossier	2023027329
Make	Peugeot 208 1.2PT 75 Active Pa
Mileage	68212
First registration	12/05/2023
client availability date	22/07/2026
inspectionDate	28/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
28	Front / Calendar / Replace	Y
38	Front Bonnet / Insulation / Replace	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
110	Wing Rear Left // Smart Repair Small	Y
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
538	Trunk Compartment / Boot Cover / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Side View Mirror Left // Painting-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Door Front Left // Smart Repair Small-scratch



Front / Calendar / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Wheel Front Right / Wheel Cover / Replace-scratch



Bumper Front // Painting-scratch



Wing Rear Right // Repair & Painting-dent



Rocker Panel Left // Smart Repair Medium-dent



Wing Rear Left // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Bumper Rear // Repair & Painting-cracked



Front Bonnet / Insulation / Replace-cracked



Trunk Compartment / Boot Cover / Replace-missing