

INSPECTION REPORT



End of contract

GENERAL INFO

File	316182
License plate	2CES117
Vehicle identification number	TMBJC9NY8NF049885
Dossier	2021302084
Make	Skoda Enyaq 80
Mileage	134101
First registration	27/06/2022
client availability date	29/06/2026
inspectionDate	17/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
14	Bumper Front // Repair & Painting	N
41	Windshield // Replace	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
145	Back Side / Logo / Replace	Y
153	Rear Bonnet // Painting	Y
161	Roof // Smart Repair Medium	N
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	Y
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
341	Wheel Alloy Front Right // Repair	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
560	Interior / A Pillar Cover / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Roof // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Front Left / Trim / Replace-scratch



Interior / A Pillar Cover / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Rear Right // Repair & Painting-dent




Roof // Smart Repair Medium-dent



Door Rear Right // Repair & Painting-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Windshield // Replace-cracked



Back Side / Logo / Replace-missing



Interior Cleaning // Small-stain



Lettering Removal 15min-Remainder stickers