

INSPECTION REPORT



End of contract


GENERAL INFO

File	318442
License plate	JV5925
Vehicle identification number	VR3USHNSSNJ662312
Dossier	2021342046
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	81533
First registration	28/07/2022
client availability date	20/07/2026
inspectionDate	23/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
237	Wing Front right / Trim / Replace	N
272	Bumper Front / Trim Right / Replace	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	Y
19	Bumper Front / Lower Cover Not Painted / Replace	N
38	Front Bonnet / Insulation / Replace	N
67	Wing Front Left / Trim / Replace	Y
81	Door Front Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
139	Bumper Rear / Spoiler / Replace	N
159	Rear Bonnet / Rear Window / Replace	Y
181	Wing Rear Right // Smart Repair Medium	Y
187	Wing Rear Right / Trim / Replace	N
201	Rocker Panel Right // Smart Repair Medium	Y
211	Door Front Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	Y
340	Wheel Two Tone Front Right // Repair	Y
774	Interior / Side Cover rear Seat / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures




Front Bonnet / Insulation / Replace-cracked



Interior Cleaning // Small-stain



Wing Rear Right / Trim / Replace-scratch



Side View Mirror Right // Painting-scratch



Door Front Right // Smart Repair Medium-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Rocker Panel Right // Smart Repair Medium-scratch



Wing Rear Right // Smart Repair Medium-scratch



Wheel Two Tone Front Right // Repair-scratch




Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front // Painting-scratch



Bumper Front / Trim Right / Replace-scratch



Wing Front right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent