

INSPECTION REPORT


End of contract

GENERAL INFO

File	317520
License plate	2DPG763
Vehicle identification number	VR3UPMHDP5042492
Dossier	2023027311
Make	Peugeot 208 1.2PT 75 Active Pa
Mileage	75860
First registration	12/05/2023
client availability date	20/07/2026
inspectionDate	28/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
31	Front Bonnet // Smart Repair Small	Y
41	Windshield // Replace	N
81	Door Front Left // Smart Repair Medium	Y
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	N
314	Wheel Front Left / Wheel Cover / Replace	N
324	Wheel Rear Left / Wheel Cover / Replace	N
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	N
540	Interior // Repair 1	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear // Polish-scratch



Wheel Rear Left / Wheel Cover / Replace-scratch



Door Front Left // Smart Repair Medium-scratch



Wheel Front Left / Wheel Cover / Replace-scratch



Bumper Front // Painting-scratch




Wheel Front Right / Wheel Cover / Replace-scratch



Wheel Rear Right / Wheel Cover / Replace-scratch



Front Bonnet // Smart Repair Small-dent



Windshield // Replace-cracked



Interior // Repair 1-missing