

INSPECTION REPORT


End of contract

GENERAL INFO

File	317818
License plate	2BJZ161
Vehicle identification number	YV1XZBWVFN2716151
Dossier	2021180058
Make	Volvo XC40 T4 PHEV Inscript.Ex
Mileage	90856
First registration	14/12/2021
client availability date	10/07/2026
inspectionDate	22/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
18	Bumper Front / Spoiler / Replace	N
80	Door Front Left // Smart Repair Small	Y
81	Door Front Left // Smart Repair Medium	Y
111	Wing Rear Left // Smart Repair Medium	N
136	Bumper Rear // Polish	Y
154	Rear Bonnet // Repair & Painting	Y
181	Wing Rear Right // Smart Repair Medium	N
193	Door Rear Right // Painting	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	N


Damage Pictures




Door Rear Right // Painting-scratch



Bumper Rear // Polish-scratch



Door Front Left // Smart Repair Small-scratch



Door Front Left // Smart Repair Medium-scratch




Bumper Front / Spoiler / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Left // Smart Repair Medium-scratch + dent



Wing Rear Right // Smart Repair Medium-scratch + dent



Rear Bonnet // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain