

INSPECTION REPORT




End of contract

GENERAL INFO

File	317632
License plate	2ARZ353
Vehicle identification number	VF3MRHNSUMS083468
Dossier	2020 359 021
Make	Peugeot 3008 1.2PTech 96kW All
Mileage	63551
First registration	28/06/2021
client availability date	06/07/2026
inspectionDate	28/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
237	Wing Front right / Trim / Replace	N
38	Front Bonnet / Insulation / Replace	N
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
136	Bumper Rear // Polish	Y
191	Door Rear Right // Smart Repair Medium	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
411	Seat Front Left // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Door Rear Right // Smart Repair Medium-scratch



Door Rear Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rocker Panel Right // Smart Repair Medium-dent



Front Bonnet / Insulation / Replace-cracked



Seat Front Left / Bottom Coating / Replace-worn



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Bumper Rear // Polish-scratch



Seat Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch



Bumper Front // Painting-scratch



Wing Front right / Trim / Replace-scratch