

INSPECTION REPORT

End of contract

GENERAL INFO

File	318895
License plate	AR5368
Vehicle identification number	VF3MCYHZUP5049128
Dossier	2023030021
Make	Peugeot 5008 1.5Hdi130 Active
Mileage	120260
First registration	24/04/2023
client availability date	28/07/2026
inspectionDate	04/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
114	Wing Rear Left // Repair & Painting	N
117	Wing Rear Left / Trim / Replace	N
16	Bumper Front // Polish	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
28	Front / Calendar / Replace	Y
40	Windshield // Repair	Y
91	Rocker Panel Left // Smart Repair Medium	N
101	Door Rear Left // Smart Repair Medium	N
191	Door Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	N
211	Door Front Right // Smart Repair Medium	N
341	Wheel Alloy Front Right // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures



Bumper Front / Lower Cover Not Painted / Replace-scratch + dent




Door Rear Right // Smart Repair Medium-scratch + dent



Windshield // Repair-glass damage



Interior Cleaning // Small-stain



Bumper Front // Polish-scratch



Front / Calendar / Replace-dent



Door Rear Left // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Right // Smart Repair Medium-scratch + dent



Wheel Alloy Front Right // Repair-scratch



Wing Rear Left / Trim / Replace-scratch



Wing Rear Left // Repair & Painting-scratch + dent