

INSPECTION REPORT

End of contract

GENERAL INFO

File	318889
License plate	GM4503
Vehicle identification number	W0VZCYHZ8M6823249
Dossier	2021159036
Make	Opel GrandlandX 1.5TD130 Eleg
Mileage	196798
First registration	15/06/2021
client availability date	28/07/2026
inspectionDate	30/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
31	Front Bonnet // Smart Repair Small	N
38	Front Bonnet / Insulation / Replace	N
91	Rocker Panel Left // Smart Repair Medium	Y
100	Door Rear Left // Smart Repair Small	Y
107	Door Rear Left / Trim / Replace	Y
110	Wing Rear Left // Smart Repair Small	N
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
174	Light / Rear Right / Replace	N
194	Door Rear Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	N
340	Wheel Two Tone Front Right // Repair	Y
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
618	Front Left Door Interior Coating / Door Handle / Replace	N
624	Front Right Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Light / Rear Right / Replace-scratch



Side View Mirror Right // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Rear Left / Trim / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Wing Rear Left // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-dent



Door Rear Left // Smart Repair Small-dent



Front Bonnet // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Front Left Door Interior Coating / Door Handle / Replace-cracked




Front Bonnet / Insulation / Replace-tear



Tyre Rear Right // Replace-tear



Interior Cleaning // Small-stain



Interior // Repair 1-bad position