

INSPECTION REPORT


End of contract

GENERAL INFO

File	317137
License plate	2DFT811
Vehicle identification number	VXKUBYHTKP4014282
Dossier	2022 192 141
Make	Opel Corsa 1.5D 102 Edition
Mileage	44971
First registration	06/03/2023
client availability date	02/07/2026
inspectionDate	07/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
341	Wheel Alloy Front Right // Repair	N
346	Tyre Front Right // Replace	N
16	Bumper Front // Polish	Y
83	Door Front Left // Painting	Y
100	Door Rear Left // Smart Repair Small	N
124	Light / Rear left / Replace	Y
156	Rear Bonnet // Polish	Y
165	Roof // Polish	Y
182	Wing Rear Right // Smart Repair Large	N
205	Rocker Panel Right // Polish	Y
222	Side View Mirror Right // Painting	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
611	Front Left Door Interior Coating // Repair	Y
883	Key Price Range 2 //	N

Damage Pictures



Roof // Polish-scratch



Rocker Panel Right // Polish-scratch



Side View Mirror Right // Painting-scratch



Bumper Front // Polish-scratch




Door Front Left // Painting-scratch



Light / Rear left / Replace-scratch



Rear Bonnet // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Front Left Door Interior Coating // Repair-scratch



Door Rear Left // Smart Repair Small-dent



Wing Rear Right // Smart Repair Large-scratch + dent



Bumper Rear // Polish-scratch



Wing Rear Left // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Tyre Front Right // Replace-tear