

INSPECTION REPORT

End of contract

GENERAL INFO

File	317935
License plate	2FGJ016
Vehicle identification number	W1K5J8FB6RN472736
Dossier	2023 170 289
Make	Mercedes CLA 250 e AMG Line A
Mileage	70036
First registration	30/04/2024
client availability date	29/07/2026
inspectionDate	04/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
244	Light / Front Right / Replace	N
272	Bumper Front / Trim Right / Replace	N
35	Front Bonnet // Polish	Y
63	Wing Front Left // Painting	Y
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
165	Roof // Polish	Y
194	Door Rear Right // Repair & Painting	Y
210	Door Front Right // Smart Repair Small	Y
282	Bumper Rear / Trim Center / Replace	N
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N

Damage Pictures



Wing Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Roof // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wing Rear Left // Polish-scratch



Door Front Right // Smart Repair Small-dent



Door Rear Right // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Rear / Trim Center / Replace-cracked



Front Bonnet // Polish-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front / Trim Right / Replace-scratch



Light / Front Right / Replace-scratch





Bumper Front // Painting-scratch