

INSPECTION REPORT

End of contract

GENERAL INFO

File	318693
License plate	MP0176
Vehicle identification number	W0VZ4DGZXP6021734
Dossier	2022066019
Make	Opel Grandland PHEV 180 Ultima
Mileage	61139
First registration	26/06/2023
client availability date	24/07/2026
inspectionDate	29/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
117	Wing Rear Left / Trim / Replace	N
131	Bumper Rear // Smart Repair Medium	N
41	Windshield // Replace	Y
84	Door Front Left // Repair & Painting	N
151	Rear Bonnet // Smart Repair Medium	Y
159	Rear Bonnet / Rear Window / Replace	N
162	Roof // Painting	N
186	Wing Rear Right // Polish	Y
187	Wing Rear Right / Trim / Replace	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
272	Bumper Front / Trim Right / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	N
684	Charger Cable //	N
860	Interior Cleaning // Small	N

Damage Pictures



Roof // Painting-scratch



Bumper Front / Trim Right / Replace-scratch




Front Right Door Interior Coating // Replace Completely-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Door Front Left // Repair & Painting-scratch + dent




Windshield // Replace-glass damage



Interior Cleaning // Small-dirty



Door Rear Right // Painting-scratch



Wing Rear Right / Trim / Replace-scratch



Wing Rear Right // Polish-scratch



Rear Bonnet // Smart Repair Medium-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Smart Repair Medium-scratch



Wing Rear Left / Trim / Replace-scratch