

INSPECTION REPORT


End of contract


GENERAL INFO

File	318802
License plate	AR5366
Vehicle identification number	VF3MCYHZUPS049148
Dossier	2023030018
Make	Peugeot 5008 1.5Hdi130 Active
Mileage	77785
First registration	24/04/2023
client availability date	27/07/2026
inspectionDate	03/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	N
80	Door Front Left // Smart Repair Small	Y
137	Bumper Rear // Replace without painting	N
213	Door Front Right // Painting	Y
237	Wing Front right / Trim / Replace	N
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Wing Front right / Trim / Replace-scratch + dent



Wheel Alloy Front Right // Repair-scratch



Door Front Right // Painting-scratch



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Replace without painting-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front // Painting-scratch