

INSPECTION REPORT

End of contract

GENERAL INFO

File	316164
License plate	2ABV291
Vehicle identification number	VF3MCYHZULS311282
Dossier	2020 287 020
Make	Peugeot 5008 1.5BHDi 96kW GT P
Mileage	258198
First registration	12/02/2021
client availability date	24/06/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
104	Door Rear Left // Repair & Painting	N
113	Wing Rear Left // Painting	N
117	Wing Rear Left / Trim / Replace	N
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
217	Door Front Right / Trim / Replace	N
801	See External Expertise	N
11	Bumper Front // Smart Repair Medium	N
39	Engine Compartment / Silencer / Replace	N
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	N
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	Y
136	Bumper Rear // Polish	Y
157	Rear Bonnet / Trim / Replace	Y
174	Light / Rear Right / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
216	Door Front Right // Polish	Y
236	Wing Front right // Polish	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
411	Seat Front Left // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
554	Central Console // Replace Completely	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	N

641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N

Damage Pictures



Door Front Left // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Bumper Front // Smart Repair Medium-scratch + dent



Engine Compartment / Silencer / Replace-tear



Interior Cleaning // Small-stain



Seat Front Left / Bottom Coating / Replace-worn



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wing Rear Right // Repair & Painting-scratch + dent



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch





Central Console // Replace Completely-scratch



Seat Front Left // Repair-scratch




Rear Left Door Interior Coating // Repair-scratch



Door Front Right // Polish-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch



Wheel Two Tone Rear Left // Repair-scratch



Bumper Rear // Polish-scratch



Light / Rear Right / Replace-scratch



Rear Bonnet / Trim / Replace-scratch



Light / Rear left / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch




Wing Rear Left / Trim / Replace-scratch



Wing Rear Left // Painting-scratch




Door Rear Left // Repair & Painting-scratch + dent




Door Front Right / Trim / Replace-dent





See External Expertise-Splashes





Door Rear Right / Trim / Replace-dent



Door Rear Right // Repair & Painting-scratch + dent



Wing Rear Right / Trim / Replace-scratch