

INSPECTION REPORT

End of contract

GENERAL INFO

File	316499
License plate	2ARN212
Vehicle identification number	TMAJD812DNJ036742
Dossier	2021019115
Make	Hyundai Tuc.TGDi PHEV 195kW 4x
Mileage	46204
First registration	22/06/2021
client availability date	06/07/2026
inspectionDate	14/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
95	Rocker Panel Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
205	Rocker Panel Right // Polish	Y
237	Wing Front right / Trim / Replace	Y
340	Wheel Two Tone Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Rocker Panel Left // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Wing Front right / Trim / Replace-scratch



Rocker Panel Right // Polish-scratch