

INSPECTION REPORT





End of contract

GENERAL INFO

File	316263
License plate	2DBL917
Vehicle identification number	TMBER6NW9P3071928
Dossier	2022103083
Make	Skoda Scala 1.0TSI 81kW Clever
Mileage	106677
First registration	25/01/2023
client availability date	01/07/2026
inspectionDate	11/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
32	Front Bonnet // Painting	N
40	Windshield // Repair	Y
71	Side View Mirror Left // Plastic Repair	N
91	Rocker Panel Left // Smart Repair Medium	N
110	Wing Rear Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	N
182	Wing Rear Right // Smart Repair Large	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	Y
417	Seat Front Left / Headrest / Replace	Y
549	Interior / Headliner/ Replace	N
561	Dashboard // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
631	Rear Left Door Interior Coating // Repair	Y
774	Interior / Side Cover rear Seat / Replace	Y
880	Emergency Key //	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Rear Left Door Interior Coating // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Wheel Alloy Front Left // Repair-scratch



Side View Mirror Left // Plastic Repair-scratch




Wheel Alloy Rear Left // Repair-scratch



Bumper Rear // Polish-scratch



Front Bonnet // Painting-scratch



Bumper Front // Painting-scratch



Seat Front Left / Headrest / Replace-scratch



Dashboard // Repair-scratch




Wing Rear Left // Smart Repair Small-dent



Trunk Lid Interior Coating / Complete Panel / Replace-scratch + dent



Wing Rear Right // Smart Repair Large-scratch + dent




Rocker Panel Left // Smart Repair Medium-scratch + dent



Interior / Headliner/ Replace-scratch + dent



Windshield // Repair-cracked



Emergency Key //-missing