

INSPECTION REPORT





End of contract

GENERAL INFO

File	317835
License plate	2BQE534
Vehicle identification number	TMBJN7NP5N7028363
Dossier	2021053040
Make	Skoda Sup.Comb.TSI 150 Clever
Mileage	91951
First registration	11/02/2022
client availability date	10/07/2026
inspectionDate	22/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
153	Rear Bonnet // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
193	Door Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	Y
234	Wing Front right // Repair & Painting	Y

Damage Pictures




Rear Bonnet // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Front // Smart Repair Large-scratch




Side View Mirror Right // Painting-scratch



Door Front Right // Painting-scratch



Door Rear Right // Painting-scratch



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wing Front right // Repair & Painting-scratch + dent