

INSPECTION REPORT



End of contract


GENERAL INFO

File	314567
License plate	2APJ462
Vehicle identification number	W1N2476101W127488
Dossier	2020 149 076
Make	Mercedes GLB 180d Business Sol
Mileage	105187
First registration	02/06/2021
client availability date	12/06/2026
inspectionDate	02/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
31	Front Bonnet // Smart Repair Small	Y
67	Wing Front Left / Trim / Replace	Y
80	Door Front Left // Smart Repair Small	Y
92	Rocker Panel Left // Painting	Y
103	Door Rear Left // Painting	Y
110	Wing Rear Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
193	Door Rear Right // Painting	Y
216	Door Front Right // Polish	Y
282	Bumper Rear / Trim Center / Replace	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	Y
341	Wheel Alloy Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	Y
540	Interior // Repair 1	Y
569	Dashboard / Steering Wheel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	N
644	Rear Right Door Interior Coating // Replace Completely	N

Damage Pictures



Bumper Rear // Polish-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Rear Right // Painting-scratch



Door Front Right // Polish-scratch



Rocker Panel Left // Painting-scratch



Wheel Alloy Rear Left // Repair-scratch





Door Front Left // Smart Repair Small-scratch



Door Rear Left // Painting-scratch



Bumper Rear / Trim Center / Replace-scratch



Trunk Compartment / Boot Cover / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Bumper Front // Smart Repair Large-scratch



Wing Front Left / Trim / Replace-scratch




Rear Left Door Interior Coating // Replace Completely-scratch



Front Bonnet // Smart Repair Small-dent



Wing Rear Left // Smart Repair Small-dent



Interior // Repair 1-missing



Dashboard / Steering Wheel / Replace-worn



Wheel Alloy Front Left // Repair-Chipped paint