

INSPECTION REPORT



End of contract

GENERAL INFO

File	316042
License plate	2AUU021
Vehicle identification number	TMAJE812DNJ044174
Dossier	2021 049 008
Make	Hyundai Tuc.TGDi PHEV 195kW 4x
Mileage	64531
First registration	27/07/2021
client availability date	03/07/2026
inspectionDate	22/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Dashboard / Steering Wheel / Replace-worn