

INSPECTION REPORT


End of contract

GENERAL INFO

File	318372
License plate	MN9176
Vehicle identification number	YV1LFK2VCM1742803
Dossier	2020 336 014
Make	Volvo XC90 B5 235 AWD Inscr. 7
Mileage	79430
First registration	10/03/2021
client availability date	17/07/2026
inspectionDate	22/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
66	Wing Front Left // Polish	Y
78	Side View Mirror Left / Direction Indicator / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
194	Door Rear Right // Repair & Painting	Y
199	Door Rear Right / Window / Replace	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
540	Interior // Repair 1	N
541	Interior // Repair 2	N
840	Interior Cleaning // Large	N

Damage Pictures



Bumper Front // Smart Repair Large-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Rear Right / Window / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear // Painting-scratch



Side View Mirror Left / Direction Indicator / Replace-scratch



Wing Front Left // Polish-scratch



Interior // Repair 2-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Right // Repair & Painting-bad repair



Interior Cleaning // Large-dirty



Interior // Repair 1-tear



Seat Front Left / Bottom Coating / Replace-worn