

INSPECTION REPORT





End of contract


GENERAL INFO

File	316369
License plate	2ABC718
Vehicle identification number	VF3LCYHZKMS017480
Dossier	2020 297 128
Make	Peugeot 308 SW 1.5BHDi 130 Bus
Mileage	119495
First registration	05/02/2021
client availability date	26/06/2026
inspectionDate	03/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
221	Side View Mirror Right // Plastic Repair	N
222	Side View Mirror Right // Painting	N
12	Bumper Front // Smart Repair Large	N
41	Windshield // Replace	Y
72	Side View Mirror Left // Painting	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	Y
104	Door Rear Left // Repair & Painting	Y
134	Bumper Rear // Repair & Painting	N
161	Roof // Smart Repair Medium	Y
163	Roof // Repair & Painting	N
166	Roof / Antenna / Replace	N
175	Light / Rear Right On Rear Bonnet / Replace	Y
194	Door Rear Right // Repair & Painting	N
271	Bumper Front / Trim Left / Replace	N
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
538	Trunk Compartment / Boot Cover / Replace	N
544	Interior / Floor Covering / Replace	Y
551	Central Console // Repair	N
569	Dashboard / Steering Wheel / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
840	Interior Cleaning // Large	N
883	Key Price Range 2 //	N

Damage Pictures



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Bumper Front // Smart Repair Large-scratch



Door Rear Right // Repair & Painting-dent



Roof // Smart Repair Medium-dent




Bumper Rear // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Roof // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent




Bumper Front / Trim Left / Replace-cracked



Trunk Compartment / Boot Cover / Replace-cracked





Roof / Antenna / Replace-missing



Interior Cleaning // Large-stain




Interior / Floor Covering / Replace-hole



Dashboard / Steering Wheel / Replace-scratch



Windshield // Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Light / Rear Right On Rear Bonnet / Replace-scratch




Door Front Left // Smart Repair Medium-scratch



Side View Mirror Left // Painting-scratch



Central Console // Repair-scratch



Side View Mirror Right // Plastic Repair-scratch



Side View Mirror Right // Painting-scratch